Oil Field Environmental Incident Summary

Responsible Party: GADECO, LLC Well Operator: GADECO, LLC Well Name: ALEXANDER 26-35-3H

Field Name: EPPING Well File #: 24124

Date Incident:5/31/2015Time Incident:18:00Facility ID Number:County:WILLIAMSTwp: 155Rng: 99Sec: 26Qtr:

Location Description: 5 miles north of 1804 on 124th street, well site and adjacent field of spring

wheat

Submitted By: 0 Gilkey Received By:

Contact Person: Billy Franklin

3600 SOUTH YOSEMITE ST

STE 900

DENVER, CO 80237-7490

General Land Use: Other - Described Above Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 5 Barrels

Brine

Other

Description of Other Released Contaminant:

produced fluids from well mostly oil

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

No immediate risks, pooled liquids are being sucked up by vac truck

Areal Extent:

~500 yds by 300 yds, Approx 50 yards in to field adjacent wellsite along west edge

Potential Environmental Impacts	\$.
none at this time	

Action Taken or Planned:

reviewed packer specs and setting procedure

Wastes Disposal Location: fluids recovered will be recycled into tanks to be treated

Agencies Involved:

Updates

Date: 6/3/2015 Status: Reviewed - Follow-up Required Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release impacted areas off location. Followup is required.

Date: 8/11/2015 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 8/11/2015.

Impacted area distinctly visible with only weeds present. More work needs to be done at location.

More follow-up is necessary.

Date: 10/5/2016 Status: Inspection Author: Washek, Sandi

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 11:30 a.m. Wind west at 35 mph, and temperature was 34 degrees F. The area of impact is in a field located west of the oil pad. Inspection of the site and walking of the field showed the field had been cultivated, planted with flax and harvested. No visible signs of stained soil or bare areas of vegetation in the field. Due to rain the past week, water was puddled in some areas of the field along the pad, but no visible sheen was seen. Check to see where waste was disposed of. No additional follow-up needed for this site.